U.S. WAR DEPT.

1) 113 TM5:1080 1942

11113.2 TM5:1080 1942

Digitized by Google



Digitized by Google

WAR DEPARTMENT TECHNICAL MANUAL

Us Dut & army

PEG TOOTH HARROW

McCORMICK DEERING NO. 2 EASY FOLD

(FOUR SECTION - 140 TEETH)
INTERNATIONAL HARVESTER

This is a reprint of TM 5-1080, Peg Tooth Harrow, McCormick Deering No. 2 Easy Fold (Four Section-140 Teeth), International Harvester. No distribution will be made to personnel possessing the original publication.

WAR DEPARTMENT · 26 NOVEMBER 1942

UNIVERSITY OF CALIFORNIA



WAR DEPARTMENT TECHNICAL MANUAL T M 5-1080

PEG TOOTH HARROW

McCORMICK DEERING NO. 2 EASY FOLD (FOUR SECTION - 140 TEETH) INTERNATIONAL HARVESTER



WAR DEPARTMENT

26 NOVEMBER 1942



WAR DEPARTMENT, Washington 25, D. C., 26 November 1942

TM 5-1080, Peg Tooth Harrow, McCormick-Deering, No. 2 Basy
Fold (Four Section-140 Teeth), International Harvester,
is published for the information and guidance of all concerned.

A.G. 062.11 (26 Apr. 41).

By order of the Secretary of War:

OFFICIAL:

J. A. ULIO, Major General, The Adjutant General. G. C. MARSHALL, Chief of Staff.

1942 **

INSTRUCTIONS FOR SETTING UP

Remove all wires and arrange parts conveniently.


Lubricate all moving parts and see that they work freely.

Bolts must be used in the holes in which they are found, or in parts to which they are attached, unless otherwise shown.

Shaded portions in the illustrations show parts to be assembled; these must be placed on the machine in the order numbered.


Wherever the terms "left" and "right" are used, it should be understood to mean from a position behind and facing the machine.

We reserve the right to make changes or improvements in the design or construction of any part without incurring the obligation to install such changes on any machine previously delivered.



Illust. 1


- 1. Attach lever end and quadrant support to tooth bar.
- 2. Attach quadrant to set lever bar.
- 3. Attach lever to lever end.
- 4. Reverse the teeth in No. 5 tooth bar as illustrated.



Ill

Place the harrow sections side by side and atta

(Also set



ist. 2

th the drawbar as shown in the above illustration.


page 8.)

PARTS LIST AND ILLUSTRATIONS

The following pages contain parts list and illustrations of "exploded" views of the various units disassembled so that parts wanted may be readily located. Reference numbers only are shown in the illustrations, and to avoid errors and delays when ordering parts, always use the regular "Part Number" shown with the "Ref. No." Do not use reference numbers when ordering parts.

Standard parts such as bolts, nuts, cotters, etc., having no IHC part number, should be ordered by size.


SET LEVER AND SET LEVER BAR



| Ref. No. | I H C Part No. | Description | No. Used Per Section |
|-------------|-------------------|---------------------------------------|-------------------------|
| 1 | | *Cotter, 1/4 x 7/8" | 1 |
| 2 3 | No. 1X | *Spring | 1 |
| 3 | P 34291 | *Latch rod | 1 |
| 4 | HB 772 | *Thumb latch | 1 |
| _ | P 34303 | *Lever | 1 |
| 5 | P 34503 | Lever, complete | 1 |
| 6 | P 34502 | Lever and quadrant support | 1 |
| 7 | P 4182 | *Slide plunger | 1 |
| 8 | P 4183 | Lever end | 1 |
| 9 | | Carriage bolt, 7/16 x 2" | 1 |
| 10 | P 4181 | Quadrant | 1 |
| 11 | P 34292 | Spacer | 1 |
| 12 | P 34501 | Set lever bar | 1 |
| 13 | | Machine bolt, $7/16 \times 1-1/8^{m}$ | 2 |
| 14 | | Machine bolt, 7/16 x 2-3/4" | 1 |
| 15 | PB 1173 | Standard | 3 |
| 16 | | Carriage bolt, 7/16 x 1-5/8" | 4 |
| 17 | | Cotter, 3/16 x 1" | 4 |
| 18 | PA 1217 | Standard | ī |

^{*} Part of lever complete (P 34503).

HARROW FRAME




Unnumbered parts in the illustrations are the same as corresponding parts shown with numbers.

| Ref. | IHC Part No. | Description | No. Used Per Section |
|------|-----------------|----------------------------------|-------------------------|
| 1 | No. 9902 | Frame bar, front | |
| 2 | # 9899 | Frame bar, center | |
| 8 | " 9909 | Tooth bar, No. 1 and No. 3 | 2 |
| 4 | 12415 | Side bar, right | |
| 5 | w 9911 | Tooth bar, No. 2 | 1 |
| 6 | # 9910 | Tooth bar, No. 4 and No. 5 | |
| 7 | # 12416 | Side bar. left | |
| 8 | W 13241 | WUW bolt. | 10 |
| 9 I | # 6702 | Rivet, 17/32 x 21/32" (rd. head) | 10 |
| 10 | # 12875 | Footh box connection | |
| 11 | | Square nut, 7/16" | 70 |
| 12 | No.13240 | "Ü" bolt. | |
| 13 | P 23931 | Peg tooth | |
| 14 | P 23932 | Runner tooth. | 4 |

Don't order parts from the illustrations only; refer to the list also.



DRAW BAR



| numbers. |
|---|
| 趋 |
| parts shown with numl |
| ng. |
| tions are the same as corresponding parts s |
| 8 |
| same |
| 룬 |
| are |
| illustrations are the same as |
| 3 |
| <u>.</u> |
| parts in th |
| nnumbered part |
| Ę |

| | No. Used | <u>н</u> ФФФ44884 | İ |
|--|---------------------|--|---|
| Sporting parts snown were numbers. | Description | Washer, 9/16 x 1-1/2" x 11 ga' Link for hooks Hook on draw bar Draw bar tie bolt Draw bar, rear Splice plate Clevis for sheave | |
| | I H C Part No. | Q 3832 No. 591 No. 1607 No. 13988 P 23932 P 13961 P 13961 | When ordering, always use I H C Part Nos. |
| 3 | Ref. No. | 01 11321 2311 2411 2611 2611 | ys use I |
| 1115 3411 | No. Ref Used No. | 8 8 8 444804 | g, alwa |
| כיווייייויסבינת במוב ביות ביות המשנימיים מיוב מווב שמווב כם כיווב ביות מונים ביות מונים ביות מונים ביות המובים | Description | No.1603RF Twisted link | When orderin |
| | I H C Part No. | No.1603RF No.12591 P 23530 P 13915 Z 287 P 14758 P 23531 P 23539 P 23539 | |
| | Ref. | പെൽ 184101012 00 | |

98_61170_1961





Manufactured by
GAYLORD BROS. Inc.
Syracuse, N. Y.
Stockton, Calif.

MON-CIRCULATING EQUI

Google

Digitized by Google